


Sketch showing for replacement of broken or 9m pole & 01 nos psc poles at Deepak Saldan Estate, due to Heavy wind & Raining at Nore Village Aurhulli section.



INDEX


-*	Existing 11KV line
⊗	proposed replacement of broken 9m psc pole
⊠	proposed replacement of broken 9m pole
Ω	proposed Guy wire

LOCATION :- Anthoni Estate

FEEDER :- Malasaway

CAPACITY :- 25KVA


D.T.C. CODE :- 436252



INDEX	
	EXISTING 25KVA TRANSFORMER
	EXISTING 11KV D.O.L.
	EXISTING LT WIRE 3Ø
	Broken pole need to be replaced (8m)
	proposed Guy wire (8m)
	proposed Releasing & Restoring of Conductor.

Sketch showing for replacement of broken 1 nos 9m RCC pole due to heavy wind and rain tree fallen on the existing Kesagodu feeder 11kv line at Mogasavara village limits in arehalli section.
 (near Side RR no-~~010005~~) MGVL-18


SKETCH :-



— X —	Existing HT Line
☒ X	Broken pole need to replaced - 9m RCC pole
— A — B	Proposed releasing & Restraining of conductor

MAGASAVARA, BAKRAVALI ROAD 63 KVA

4362 ~~019~~
fy



INDEX

☒	Existing DIC
-x	Existing LT line
⊗	Broken sum pole
	poles need to be replaced
	3 nos