CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED

ESTIMATE NO: MD/BD-05

Dato: 10/06/2022

Estimate for replacement of damaged poles in BC halli NJY and Bhugathahalli I feeder double circuit at Gadijogi hundi village in Madigahalli O&M Section, Bannu Subdivision. $\sqrt{-16HS1/\gamma-17344/05.5.52}$

211	Name of the materials	Unit —	N	Materials Cost		L/C	
o.			Qnty	Rate	Amount	Rate	Amour
	RCC Pole 9 Mtrs. Long	No.	1	7153	7153	1341	1341
2	PSC Pole 9 Mtrs. Long	No.	1.	4276	4276	1341	1341
3	PSC Pole 8 Mtrs. Long	No.	1	3578	3578	1072	1072
·‡	11KV .5 KN polymeric Pin Insulator	No.	21	221	4641	0	0
5	Straightening of 8 Mtrs RCC/ PSC ooles	No.	3	0	0	304	2412
6	Rabbit ACSR Conductor with 1.5% Sag for HT Lines	Kms.	0.360	61515	3299	2869	1033
7	Contingencies at 3% on item(5)	Kms.	n		99		0
8	1 1kv pin insulators	Set	0	65	0	0	0
ŋ	Releasing & restringing of Rabbit ACSR conductor	Kms.	2.700	0	0	6268	16923
10	Releasing & restringing of 2 ACSR conductor	Kms.	0.800	0	0	4598	3678
11	Guy Set Complete	Set	1	1209	1209	390	390
12	11KV Horizontal X-Arms with HT ST Supports	No.	7	668	4676	122	854
13	Release & refixing of 11KV Horizontal X- Arms with HT ST Supports	Set	5	0	0	231.8	115
14	Release & refixing of 4 Pin X- Arms	Set	3	0	0	231.8	695
15	Release & refixing of Service main	No.	15			75	112
16	Loading & unloading of 9M poles	No.	2	0	0	106	212
17	Loading & unloading of 8M poles	No.	1	0	0	79	
18	Misc. Materials+L.C.	L/s			0		
19	Sub Total				28931		323

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನಿಯರ್ (ವಿ) ಕಾ ಮತ್ತು ಪಾ ಉಪವಿಭಾಗ, ಚಾ.ವಿ.ಸ.ವಿ.ನಿ. ಬನ್ನೂರು

ಸಹಾಯಕ ಇಂಜನಿಯರ್ (ನಿ) -1-1-2-

		, ar Charges	32366	an a
1		dreak Down Charges at 25% on labour for speedy restoration of power	8091	
1	21	EEC @ 20% on Labour cost	6473	
ſ	22	CGST/ SGST @ 18% on Labour Charges	5826	
	23	Transportation Cost from stores to site @ 2% on M.C.	579	
	24	Provident Fund at 17.75% on Labour Charges	5745	
	25	Contingencies at 2% on material & Labour	1226	
		TOTAL RS.	89236	

PART-B (Decommission Estimate)

	SI.N			Labour Cost			Remarks
	0.	Name of the materials	Unit	Qnty	Rate	Labour	Remarks
	1	Labour Charges:					
		(a) Releasing of 9 Mtrs RCC/PCC poles	No.	/× 1	1206.9	1207	
C		(b) Releasing of 8 Mtrs RCC/PCC poles	No.	- 0	964.8	0	
		(c) Misc. Labour	L/S			0	
	2	Labour Charges:				1207	
	3	Break Down Charges at 25% on labour for speedy restoration of power				302	
	3	EEC @ 20% on Labour cost				241	
	4	CGST/ SGST @ 18% on Labour Charges				217	
	5	Transportation Cost from stores to site @ 2% on M.C.				0	
	6	 6 Provident Fund at 17.75% on Labour Charges 7 Contingencies at 2% on material & Labour Total Rs. 				214	
	7				2.4	 	
						3413	 -

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನಿಯರ್ (ವಿ) ಕಾ ಮತ್ತು ಪಾ ಉಪವಿಭಾಗ, ಚಾ.ವಿ.ಸ.ನಿ.ನಿ. ಬನ್ಯೂರು

-----105 2015 11 H fa

ABSTRACT			
PARTA	89236		
PART-B	3413		
Total	92649		

CERTIFICATE: .

Certified hat I have personally visited the spot and prepared this estimate by using Current SR for most economical and safe way of executing works.

REPORT:

This estimate amounting to Rs.92649/- only is prepared for replacement of damaged poles in BC halli NJY and Bhugathahalli IP feeder double circuit at Gadijogi hundi village in Madigahalli O&M Section, Bannur Subdivision. It is proposed to replace the broken RCC/ PCC poles and restringing of conductor which was damaged due to heavy wind and rain at the points shown in the sketch for restoration of power supply the consumers in BC halli NJY and Bhugathahalli IP feeder double circuit is restored supply as SOP, so please cosider the Break Down Charges at 25% on labour for speedy

restoration of power. Hence this estimate is prepared and submitted for your kind sanction.

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನಿಯರ್ (ಎ) ಕಾ ಮತ್ತು ಪಾ ಉಪವಿಭಾಗ, ಚಾ.ವಿ.ಸ.ನಿ.ನಿ ಬನ್ಸೂರು

3