


Sketch showing the Regulations of 7th Nov. 2003/11.4.02 for replacement of damaged sub REC pole by post
 sub REC pole will not be having wind frame & existing 100km TC (OS: 365795) at Jashtripura village
 and in vicinity Sacha 15.0.01-15.0.1



- ☒ :- Existing 100km TC
- ✗ :- Existing 4 Line
- ⊗ :- Damaged sub REC pole by sub REC