


Sketch Showing about Regularity of work: 30002/D-11-4-2022 for Replacement of damaged gnd psc pole by good gnd psc pole freefall on HV line of Hanchangrao feeder heavy wind & rain near Latschamiputra station (OTC: 365788) and in Arkhitya Sub 5R per 570.)



Index

~~⊗~~ :- Existing HV 4LS line

⊗ :- Existing damaged gnd psc pole by gnd psc