


Sketch showing requirements of tower 30185/11-2-8000 for replacement of bottom damage good psc pole by good psc pole due to burnt out pole near substation of 11KV line & mechanically very strong in ASIKHARY SODH  
 K.R.PET-510-1



Index

□ :- Existing OP structure.

✗ :- Existing 11KV line

⊗ :- damaged good psc pole by good psc pole