


SKETCH  
353247



→ Guysets  
⊗ Iron/Damaged poles

*M. Manjunath Prasad*  
M.Manjunath Prasad  
Asst. Executive Engineer (Ele),  
CESC, S.R.Patna Sub-Division

*C. Naveen Kumar*  
C.Naveen Kumar Junior  
Engineer (Ele) CESC,  
Naguvanahalli section S.R.Patna