


Sketch showing for replacement of broken 1nos 8m PSC by good 9m RCC pole due to heavy wind and rain tree fallen on the existing Malasavara feeder 11kv line at Bellavara village limits in Arehalli section.  
 (near Side RR no-A112)

SKETCH :-



	Existing HT Line
	Broken pole need to replaced - 9m RCC pole
	Proposed releasing & Restraining of conductor
	proposed Guy set