


Sketch showing replacement of damaged gut pipe by good gut pipe here here on new line of  
Generally feeds heavy wind rain and Vhaugisaraaya. Akikily village here is Akikily feeds  
K.R.P. 1510-7

Town: 29666 / 16.10.2021



~~X~~ :- Existing New line

(X) :- Damaged gut pipe