


CHAMUNDESHWARI ELECTRICITY SUPPLY CORPORATION LIMITED,				
Estimate No: SMR-606			Dated : 10.09.2022	
Estimate for Replacement of broken pole at Hanjugoadahalli, Harle kudige, Maragidi, neralamakki, In Hanbal section skp Sub division.				
Credit Portion:				
sl no	Particulars of Equipments	Unit		Remarks
1	2/4 pin cross arm	No	3 No * 3 Kg = 9 KG	Scrap
2	Horizontal cross arm cross arm	No	8 No * 3 Kg = 24 KG	Scrap
3	Date of commissioning		1998	
4	Dismantelling		After the sanctioning of estimates	
1	Original/Assessed value of dismantalling Assets			
2	Depreciation Earned			
3	Written down value of dismantalling assets			
AO			AAO	
Certificate: Certified that I have personally visited the spot and prepared this estimate using current S.R in most economical and safe way for execution of work.				
REPORT:-This estimate is prepared for Replacement of broken pole at Hanjugoadahalli, Harle kudige, Maragidi, neralamakki and Magajihalli, in Hanbal section in Hanbal section skp Sub division.				
Replacement of broken pole at Hanjugoadahalli-2 POLE h/lt, Harle kudige-1, Maragidi-1, neralamakki-1 and Magajihalli -5 poles, in Hanbal section				
Assistant Executive Engineer(Ele) CESC, O&M Sub-division, S.K.Pura			 Junior Engineer(Ele) CESC, O&M-4 Section, Hanbalu	